


The contractor is responsible for checking dimensions, tolerances and references. Any discrepancy to be verified with the Architect before proceeding with the works. Where an item is covered by drawings to different scales the larger scale drawing is to be worked to.

Do not scale drawing. Figured dimensions to be worked to in all cases.

CDM REGULATIONS 2015. All current drawings and specifications for the project must be read in conjunction with the Designer's Hazard and Environment Assessment Record

All intellectual property rights reserved.

Outline application boundary



P01	First Issue		
Rev	Date	Description	Dwn Ckd

Consultant
PRP prp-co.uk
 London
 020 7653 1200



Client
Peabody Trust/Dagenham Dock Ltd

Project Title
Dagenham Green

Drawing Title
Site Location Plan

Planning - Illustrative

Project	Origin	Zone	Level	Type	Role	Number
DDSP-PRP-ZZZZ-ZZ-DR-A-02004						

Revision
P01
 Status
S4

Drawn pxx Checked ci Date Sept. 2021 Scale @ A3 As indicated

Sheet Originates from Model: DDSP-PRP-ZZZZ-ZZ-M3-A-00001.rvt